


PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 555Dated: 10.02.26It is certified that an inspection team headed by Pradeep Kumar Saha, Executive Officer(Name of Officers with designation) from Talcher Municipality, Talcher(Name of Department/ Office) inspected the DAV Public School, MCL Lingaraj Area,
Devalbera Colliery, Dist - Angul, 759102(Name & Address of the school) on 10.02.26 (date of inspection) and found that theDAV, Public School, MCL Lingaraj Area,
Devalbera Colliery, (Name of school) has safe drinking water

facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

The above is valid for a period of one yearSignature with Seal: 
10.02.26Name: Pradeep Kumar Saha
Executive Officer
Talcher MunicipalityDesignation: Executive Officer
Talcher Municipality, Talcher

Name & Address of the Office / Department

To

The Principal
DAV. Public School
MCL, Lingaraj Area, Talcher
(Name & Address of the Institution)
Headmistress
DAV PUBLIC SCHOOL
MCL, LINGARAJ AREA
महा प्रबंधक
एम्. सी. एल., लिंगराज क्षेत्र
General Manager
M.C.L. Lingaraj Area